

Dominion Nuclear Connecticut, Inc.  
Millstone Power Station  
Rope Ferry Road, Waterford, CT 06385



DEC 10 2008

U. S. Nuclear Regulatory Commission  
Attention: Document Control Desk  
Washington, DC 20555

Serial No.	08-0726
MPS Lic/GJC	R0
Docket No.	50-423
License No.	NPF-49

**DOMINION NUCLEAR CONNECTICUT, INC.**  
**MILLSTONE POWER STATION UNIT 3**  
**LICENSEE EVENT REPORT 2008-003-00**  
**AUTOMATIC REACTOR TRIP DURING**  
**SHUTDOWN FOR REFUELING OUTAGE 3R12**

This letter forwards Licensee Event Report (LER) 2008-003-00 documenting a condition discovered at Millstone Power Station Unit 3 on October 11, 2008. This LER is being submitted pursuant to 10 CFR 50.73(a)(2)(iv)(A) as an event that resulted in manual or automatic actuation of systems listed in 10 CFR 50.73(a)(2)(iv)(B).

If you have any questions or require additional information, please contact Mr. William D. Bartron at (860) 444-4301.

Sincerely,

 12/10/2008

Linwood L. Morris  
Plant Manager – Nuclear

Attachments: 1

Commitments made in this letter: None

IE22  
NRK

cc: U.S. Nuclear Regulatory Commission  
Region I  
475 Allendale Road  
King of Prussia, PA 19406-1415

Ms. C. J. Sanders  
Project Manager  
U.S. Nuclear Regulatory Commission Mail Stop 08B3  
One White Flint North  
11555 Rockville Pike  
Rockville, MD 20852-2738

NRC Senior Resident Inspector  
Millstone Power Station

**ATTACHMENT**

**LICENSEE EVENT REPORT 2008-003-00**  
**AUTOMATIC REACTOR TRIP DURING**  
**SHUTDOWN FOR REFUELING OUTAGE 3R12**

**MILLSTONE POWER STATION UNIT 3**  
**DOMINION NUCLEAR CONNECTICUT, INC.**

<b>NRC FORM 366</b> <b>U.S. NUCLEAR REGULATORY COMMISSION</b> (9-2007)				<b>APPROVED BY OMB NO. 3150-0104</b>				<b>EXPIRES 08/31/2010</b>																					
<b>LICENSEE EVENT REPORT (LER)</b> (See reverse for required number of digits/characters for each block)												Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the Records and FOIA/Privacy Service Branch (1-5 F52), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollect@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NE08-10202 (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose information collection does not display a currently valid OMB control number, the NRC may not conduct or sponsor, and a person is not required to respond to, the information collection.																	
1. FACILITY NAME Millstone Power Station - Unit 3						2. DOCKET NUMBER 05000423						3. PAGE 1 OF 2																	
4. TITLE Automatic Reactor Trip During Shutdown for Refueling Outage 3R12																													
5. EVENT DATE						6. LER NUMBER						7. REPORT DATE						8. OTHER FACILITIES INVOLVED											
MO		DAY		YEAR		YEAR		SEQUENTIAL NUMBER		REV NO.		MO		DAY		YEAR		FACILITY NAME				DOCKET NUMBER							
10		11		2008		2008		003		00		12		10		2008		FACILITY NAME				DOCKET NUMBER							
10		11		2008		2008		003		00		12		10		2008		FACILITY NAME				DOCKET NUMBER							
10		11		2008		2008		003		00		12		10		2008		FACILITY NAME				DOCKET NUMBER							
9. OPERATING MODE						11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)																							
1						20.2201(b)						20.2203(a)(3)(ii)						50.73(a)(2)(ii)(B)						50.73(a)(2)(ix)(A)					
10. POWER LEVEL						20.2201(d)						20.2203(a)(4)						50.73(a)(2)(iii)						50.73(a)(2)(x)					
30						20.2203(a)(1)						50.36(c)(1)(i)(A)						X 50.73(a)(2)(iv)(A)						73.71(a)(4)					
						20.2203(a)(2)(i)						50.36(c)(1)(ii)(A)						50.73(a)(2)(v)(A)						73.71(a)(5)					
						20.2203(a)(2)(ii)						50.36(c)(2)						50.73(a)(2)(v)(B)						OTHER					
						20.2203(a)(2)(iii)						50.46(a)(3)(ii)						50.73(a)(2)(v)(C)						Specify in Abstract below or in NRC Form 366A					
						20.2203(a)(2)(iv)						50.73(a)(2)(i)(A)						50.73(a)(2)(v)(D)											
						20.2203(a)(2)(v)						50.73(a)(2)(i)(B)						50.73(a)(2)(vii)											
						20.2203(a)(2)(vi)						50.73(a)(2)(i)(C)						50.73(a)(2)(viii)(A)											
						20.2203(a)(3)(i)						50.73(a)(2)(ii)(A)						50.73(a)(2)(viii)(B)											
						12. LICENSEE CONTACT FOR THIS LER																							
NAME William D. Bartron, Supervisor Nuclear Station Licensing												TELEPHONE NUMBER (Include Area Code) 860-447-1791 x4301																	
13. COMPLETE ONE LINE FOR EACH COMPONENT FAILURE DESCRIBED IN THIS REPORT																													
CAUSE		SYSTEM		COMPONENT		MANUFACTURER		REPORTABLE TO EPIX				CAUSE		SYSTEM		COMPONENT		MANUFACTURER		REPORTABLE TO EPIX									
14. SUPPLEMENTAL REPORT EXPECTED												15. EXPECTED SUBMISSION DATE						MONTH		DAY		YEAR							
<input type="checkbox"/> YES (If yes, complete EXPECTED SUBMISSION DATE). <input checked="" type="checkbox"/> NO												DATE																	
16. ABSTRACT (Limit to 1400 spaces, i.e., approximately 15 single-spaced typewritten lines)																													
<p>On October 11, 2008, while in MODE 1 at approximately 30% power an automatic reactor trip occurred, as Millstone Power Station Unit 3 was reducing power in preparation for the 12th refueling outage. Prior to the reactor trip the plant was experiencing Steam Generator (S/G) level oscillations as the result of removing feedwater system components from service. The operators took manual control of the feedwater system, however, the oscillations increased and the 'A' S/G reached its 'high-high' set point resulting in an automatic turbine trip and feedwater isolation. A reactor trip on 'low-low' S/G level followed. All safety systems operated normally including the automatic start of the auxiliary feedwater pump, and the reactor shut down safely. All secondary systems operated normally. The cause was determined to be the operating crew on shift failed to effectively use the tools necessary to enable an event free shutdown of the plant. The organization with respect to monitoring and measuring crew performance was not effective in implementing programs designed to manage the challenges to the operators.</p> <p>Prior to start up from the refueling outage, training on low power feed station operations for on shift and active licensed operators was conducted. Additionally proper operation of the S/G water level control system and the feedwater regulating valves was verified. Additional corrective actions will be entered into the station's corrective action program.</p> <p>This event is being reported pursuant to 10 CFR 50.73(a)(2)(iv)(A) as an event that resulted in manual or automatic actuation of systems listed in 10 50.73(a)(2)(iv)(B).</p>																													

**LICENSEE EVENT REPORT (LER)**

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE
Millstone Power Station - Unit 3	05000423	YEAR	SEQUENTIAL NUMBER	REVISION NUMBER	2 OF 2
		2008	-- 003 --	00	

NARRATIVE (If more space is required, use additional copies of NRC Form 366A) (17)

**1. EVENT DESCRIPTION:**

On October 11, 2008, while in MODE 1 at approximately 30% power an automatic reactor [AB] [RCT] trip occurred, as Millstone Power Station Unit 3 (MPS3) was reducing power in preparation for the 12th refueling outage. Prior to the reactor trip the plant was experiencing Steam Generator (S/G) [SB] [SG] level oscillations as the result of removing feedwater system [SJ] components from service. In an effort to control the S/G level oscillations, the operators took manual control of the feedwater system; however, the oscillations increased to the point that the 'A' S/G reached its 'high-high' set point resulting in an automatic turbine [TRB] trip and feedwater isolation. Once the turbine tripped, the 'C' S/G level quickly shrank to its 'low-low' S/G level set point resulting in a reactor trip. All safety systems operated normally including the automatic start of the auxiliary feedwater (AFW) pump [BA] [P], and the reactor shut down safely. All secondary systems operated normally.

**2. CAUSE:**

The cause was determined to be the operating crew on shift failed to effectively use the tools necessary to enable an event free shutdown of the plant. The organization with respect to monitoring and measuring crew performance was not effective in implementing programs designed to manage the challenges to the operators.

**3. ASSESSMENT OF SAFETY CONSEQUENCES:**

With MPS3 at approximately 30% power during the down-power evolution, the S/G levels began to oscillate over a wider and wider range. The S/G oscillations increased to the point that the 'A' S/G reached its 'high-high' set point resulting in an automatic turbine trip and feed water isolation. Once the turbine tripped, the 'C' S/G quickly shrank to its 'low-low' S/G level set point resulting in a reactor trip. All safety systems operated normally and the reactor shut down safely.

As the result of the reactor trip, the AFW pump automatically started in accordance with plant design and the system operated as designed. No other mitigating systems were challenged.

The integrity of the fuel, reactor coolant system, or containment was not challenged or degraded as the result of this event.

There were no challenges to public or occupational radiation safety, or personnel safety as the result of this event.

**4. CORRECTIVE ACTION:**

Prior to start up from the refueling outage, training on low power feed station operations for on shift and active licensed operators was conducted. Additionally proper operation of the S/G water level control system and the feedwater regulating valves [FCV] was verified. Additional corrective actions will be entered into the station's corrective action program.

**5. PREVIOUS OCCURRENCES:**

LER 2005-005-00 documents an automatic reactor trip of Millstone Unit 3 due to 'low-low' steam generator level.

Energy Industry Identification System (EIIIS) codes are identified in the text as [XX].